

SCHOOL AREA IMPROVEMENTS: Sheet 2 of 3

Grand Avenue and Mountainview Avenue Intersection Improvements



Existing Conditions

- Existing concrete bus pad does not connect to crosswalk.
- No sidewalk west of bus pad on Grand Avenue.
- Parked cars reduce visibility at crosswalk on east leg.

Recommendations

- A** Extend bus pad to crosswalk and construct curb ramp leading to crosswalk.
- B** Post no-parking signs from east of intersection to 20-feet west of intersection.

Grand Avenue/Belle Avenue Crossing Improvements



Existing Conditions

- Bicycle and pedestrian path parallels Grand Avenue on the south and ends at Belle Avenue.
- No crosswalk on south leg of intersection.
- Stop sign for eastbound traffic on Grand Avenue obscured by tree.

Recommendations

- C** Stripe yellow transverse crosswalk across Belle Avenue.
- D** Construct curb ramp on northeast corner.
- E** Move stop sign for eastbound Grand Avenue traffic so it is visible.


Jewell Avenue Improvements



Existing Conditions



No sidewalk on north side of Jewell Avenue



Landscaping on Jewell Ave.



Fence on Jewell Ave.

Recommendations

- F** Construct 4-foot sidewalk on north side of Jewell Avenue from Grand Avenue to school grounds. Sidewalk will cross six driveways and require landscaping and fencing to be moved.

DRAFT
5/13/08

SAFE ROUTES TO SCHOOL IMPROVEMENT PLAN FOR COLEMAN SCHOOL