


SCHOOL AREA IMPROVEMENTS

Coleman Elementary School Area Map



Belle Avenue Crossing Improvements



Crosswalk at school entrance to pedestrian over-crossing.



Approach to crosswalk at school entrance.

Existing Conditions

- Existing mid-block crosswalk from school to pedestrian over-crossing is faded.
- School signage needs to be updated.

Recommendations

- Ⓐ Restripe high-visibility ladder-style crosswalk in front of school.
Option: Construct raised pedestrian crossing.
- Ⓑ Replace existing signs at crosswalk with Assembly B signage.
- Ⓒ Install School sign on light pole near intersection of Belle Avenue

DRAFT
5/13/08

SAFE ROUTES TO SCHOOL IMPROVEMENT PLAN FOR COLEMAN SCHOOL